




适合系统:
MACH3运动控制系统

MACH3控制卡

MKX(标准版) - 5代说明书



标准卡：184x127x30mm

型号

MK3-V: 带USB接口的，3轴运动控制卡

MK4-V: 带USB接口的，4轴运动控制卡

MK6-V: 带USB接口的，6轴运动控制卡

第2部份：英文介绍/ English Introduction

The following information describes the English



Features:

- ★ Fully supporting all Mach3 versions
- ★ Support save data when power off
- ★ Support spindle speed feedback
- ★ Support 3 meters USB cable
- ★ Supports Up 6-axis
- ★ Maximum step-pulse frequency is 2000KHz

Status indicator LED can be useful to show the USB

- ★ connection, and working status by flashing.
- ★ 16 general-purpose input, 8 output


has speed function, the spindle actual speed Mach3

- ★ interface in real-time display
- ★ all IO-port isolation, interference, stable performance
- ★ Full support for USB hot-swappable, the card is Monitoring USB connection status at any time.

第2部份：英文介绍/ English Introduction

Simple connection description

Application Connection Diagram




Support: 3-axis or 4-axis, or 6-axis

Mk3-V: 3-axis; Mk4-V: 4-axis; Mk6-V: 6-axis

第2部份：英文介绍/ English Introduction


Signal Description



第2部份：英文介绍/ English Introduction

Wiring diagram shows

NOTE: If the inverter is turned on, the control card is not working properly because of interference caused by the inverter; Replace inverter.



第2部份：英文介绍/ English Introduction

Electrical Characteristics

	Parameter Description	
axis output control:	Drive Current	Isolated open collector output; 5V, 20mA
	Drive	Pulse + direction output
	Output frequency	2000KHZ
	axes	MK3-V:3-axis;MK4-V:4-axis;MK6-V:6-axis
	Isolation Voltage	3.5KV
Spindle inverter output: 3 types of output modes	Analog voltage output	0—10V
	PWM output	5V,1KHZ, Duty:0-100%
	Pulse+direction output	5V,15HZ to 4KHZ
8 IO output	Drive Current	Isolation:50mA, 25V
	Isolation Voltage	3.5KV
16 IO intput	Input Current	Isolated inputs, 5 mA, maximum voltage 25V
	Isolation Voltage	3.5KV
USB interface	Complies with USB2.0 standard	

附件：接线图(Software installation)

软件安装 (Software installation)

● 第1步：安装MACH3软件

No.1:Install MACH3 software

● 第2步：拷贝驱动到指定的MACH3目录

No.2: copy drive to the specified MACH3 directory

具体操作：参见光盘资料..\\中文资料\\MACH3卡驱动\\《驱动安装说明.txt》
see the disc information:..\\English Manual\\usb card driver\\readme.txt

● 第3步：参见接线图，将控制卡连线正确

No.3: See wiring diagram, which will control the card connection correctly

● 第4步：用USB线将控制卡和电脑连接起来

No.4: Connect the control card and computer with the USB line.

完成以上步骤，你就可以打开MACH3软件，进行操作，使用了。

To complete the above steps, you can open the MACH3
software, and use.



参见印刷说明书：《MACH3软件参数设置》，调整脉冲当量等参数设置

See print Manual: "MACH3 parameter setting", adjust the parameters such as pulse equivalent set

附件：接线图(Annex 2:Wiring schematics)

应用接线图

MKX Wiring schematics


1. 第1步，给控制卡接上电源线

NO.1 : power input

power : 24V,0.5A



使用控制卡前，需要给控制卡提供电源
直流24V；工作电流0.5A



2. 第2步：驱动器连接：支持伺服或步进驱动器，差分输出信号


NO.2 : Drive Interface : Supporting servo or stepping drive

应用接线图

MKX Wiring schematics

3.第3步：主轴控制-变频器连接

NO.3 : Inverter Interface




应用接线图

MKX Wiring schematics


主轴控制：步进或伺服驱动器

Spindle connected stepper or servo drives



4.第4步：输出口 继电器连接：OUT3到OUT8连接继电器方式

NO.4 : Relay Interface : OUT3 to OUT8 Relay Interface




应用接线图

MKX Wiring schematics

5.第5步：16个输入口IN0-IN15接法：限位开关等接口：输入低电平有效


NO.5 : input Interface : 16 input port;In0 to In15.Active Low




新增功能

New features

断电续传：当控制卡突然断电时，当前加工程序已经加工的行数自动保存在控制卡的芯片中。(控制卡插件显示保存行数)
Break continue: when the control card suddenly power off, the control card chip automatically save the current G code line number. Control card plug-in display save the number of lines.



等到下一次控制卡通电以后,加载加工程序,点击断电续存按钮,Mach3软件自动从上一次保存的行数处开始加工。
Wait until the control card is connected to the power supply next, load the G code program, click the power to continue to the break continue button, Mach3 software automatically from the last save the number of lines to start running.




新增功能

New features


主轴速度反馈：主轴实时转速通过传感器反馈给控制卡的速度反馈接口“Speed-DEC”，然后在Mach3软件上显示RPM速度.支持反馈输入最大脉冲频率20KHZ.

Spindle speed feedback: spindle speed feedback through the sensor feedback to Input port “Speed-DEC” , and then display the RPM speed on the Mach3 software. Maximum support feedback inputPulse frequency 20KHZ.



USB高抗干扰能力：全新设计独立的USB数据处理器，防止USB通讯被干扰，更加稳定可靠.适合等离子切割和自动化焊接等.

USB anti interference: the new design of the independent USB data processor, to prevent the interference of USB communication, more stable and reliable.Suitable for plasma cutting and automatic welding and so on.





成都芯合成科技有限公司
Chengdu XinHeCheng Technology Co.,Ltd
<http://www.cdxhctech.com>

如有印刷或翻译错误，望用户谅解。产品设计和规格如有变化，恕不另行通知。
此使用手册的出版日期为2016年2月。关于此日期后上市的产品驱动程序的变化，
请登录公司网站查看并更新，或与我们售后联系。